

# Work Order

**Location:** Office

**Supervisor:** Main Supervisor

**Equipment ID:** F300-V

**Work Order #:** 1

**Description:** Ford 300 Pickup 1

**Recurring:**

**Scheduled Date:** 12/01/2018

**Miles/Hrs:** 35214

**Interval:**

**Repair Type:** Engine light

**Quantity:** 0

**Repair Notes:** Replace Faulty Feul Cap, Check Fluids and rotate tires

**Completed By:** Tom Jones

**Completion Date:** 01/15/2019

**Completion Notes:** Also Checked Fluids and Rotated Tires

### Cost Summary

**Hours:** 0.5

**Rate:** \$60.00

**Labor Cost:** \$30.00

**Other Cost:** \$5.04

**Parts Cost:** \$54.00

**Total Cost:** \$89.04

<u>Part</u>	<u>Part Number</u>	<u>Vendor</u>	<u>Invoice #</u>	<u>Qty</u>	<u>Cost</u>	<u>Ext.</u>
Feul Cap	32515	Auto Parts Store	32595	1	\$54.00	\$54.00
<b>Total Parts Cost:</b>						\$54.00